

Figure 1 DTA plots showing the glass to crystalline transition for the ALLOY A and the Gd modified GALLOY A alloys.




Figure 2 DTA plots showing the glass to crystalline transition for the ALLOY B and the Gd modified GALLOY B alloys.